

Total Air Group

2456 Winchester Rd Hgr 14
 Memphis, Tennessee 38116

September 07, 2018

Telephone: 901-396-9707

Fax: 901-396-9708

Scan Criteria

Tail Number: N335TA

Tail Number: N335TA	Manufacturer: Raytheon Aircraft Company	Total Hours: 13,613.30	Hours at Install: 1,936.50
Model: 200	Description: SUPER KINGAIR	Total Cycles: 13,272.00	Current Hours: 1,966.60

Event	Event Description	ATA	Status	Frequency	Last Compliance	Remaining	Compliance Due
Inspection	Phase 1 Inspection		Mandatory	200.00H 12cm	13,477.30h/ 09-06-2017	64.00h/ .74month	13,677.30h/ 09-30-2018
Inspection	Phase 2 Inspection		Mandatory	400.00H 12cm	13,477.30h/ 09-06-2017	264.00h/ .74month	13,877.30h/ 09-30-2018
Inspection	Phase 3 Inspection		Mandatory	600.00H 24cm	13,613.30h/ 13,272.00C/ 08-29-2018	600.00h/ 23.77month	14,213.30h/ 08-31-2020
Inspection	Phase 4 Inspection		Mandatory	800.00H 24cm	13,613.30h/ 13,272.00C/ 08-29-2018	800.00h/ 23.77month	14,413.30h/ 08-31-2020
AD	AD2004-23-02 Nose Gear Fork		Mandatory	200.00H	13,583.20h/ 13,242.00C/ 08-07-2018	169.90h	13,783.20h
AD	AD2005-01-18C Fuselage Stringers		Mandatory	500.00C	13,613.30h/ 13,272.00C/ 08-29-2018	500.00C	13,772.00C
Special Checks	91.411 & 91.413 RVSM Altimeter & Transponder Certification		Mandatory	24cm	02-19-2018	17.71month	02-29-2020
Replacement	Air Stair Latch Bolts - Side - Replacement		Mandatory	6,000.00H	13,145.90h/ 12,839.00C/ 10-22-2012	5,532.60h	19,145.90h
Replacement	Air Stair Upper Hooks - Replacement		Mandatory	10,000.00C	11,215.30h/ 11,200.00C/ 11-16-2002	7,928.00C	21,200.00C
Special Checks	Battery, Lead Acid		Mandatory	800.00H 365d	13,541.90h/ 02-27-2018	728.60h/ 173day	14,341.90h/ 02-27-2019
Inspection	FWD Pressure Bulkhead		Mandatory	2,500.00C	13,295.60h/ 13,052.00C/ 07-09-2014	2,280.00C	15,552.00C
Inspection	Cabin Door & Frame Inspection		Mandatory	1,000.00C	13,295.60h/ 13,052.00C/ 07-09-2014	780.00C	14,052.00C
Special Checks	Cabin Alt Warning System Test		Mandatory	12m			
Replacement	ELT Battery Replacement		Mandatory	60m	01-01-2015	15.81month	01-01-2020

Total Air Group

2456 Winchester Rd Hgr 14
 Memphis, Tennessee 38116

September 07, 2018

Telephone: 901-396-9707

Fax: 901-396-9708

Tail Number: N335TA		Manufacturer: Raytheon Aircraft Company		Model: 200		Description: SUPER KINGAIR	
Event	Event Description	ATA	Status	Frequency	Last Compliance	Remaining	Compliance Due
Inspection	ELT 91.207(D) Inspection		Mandatory	12m	13,613.30h/ 13,272.00C/ 08-29-2018	11.71month	08-29-2019
Special Checks	ELT Reregistration		Mandatory	2y	06-28-2015	1.19yearOVD	06-28-2017
Special Checks	Fire Ext, Cabin - Hydro		Mandatory	12y	13,332.60h/ 13,086.00C/ 12-30-2014	8.31year	12-30-2026
Special Checks	Fire Ext, Cockpit - Hydro		Mandatory	12y	13,332.60h/ 13,086.00C/ 12-30-2014	8.31year	12-30-2026
Inspection	Firewall Shutoff Valve - test or replace		Mandatory	200.00H		13,413.30h/ OVD	200.00h
Inspection	Flap Flex Shaft - Inspect		Mandatory	5,000.00C	11,215.30h/ 11,200.00C/ 11-16-2002	2,928.00C	16,200.00C
Inspection	Flow Control Unit Solenoid Valve Filter - Clean/Inspect		Mandatory	800.00H	13,613.30h/ 13,272.00C/ 08-29-2018	800.00h	14,413.30h
Inspection	Flight Control Pulleys/Brackets - Inspect		Mandatory	5,000.00C	11,215.30h/ 11,200.00C/ 11-16-2002	2,928.00C	16,200.00C
Inspection	Fuel Probe Clean/Inspect		Mandatory	2,400.00H 30m	13,613.30h/ 13,272.00C/ 08-29-2018	2,400.00h/ 29.68month	16,013.30h/ 02-28-2021
Replacement	Instrument Air Filter Replace		Mandatory	600.00H	13,295.60h/ 13,052.00C/ 07-09-2014	282.30h	13,895.60h
Inspection	Instrument Panel Stringers / Brackets - Inspect		Mandatory	10,000.00C	11,215.30h/ 11,200.00C/ 11-16-2002	7,928.00C	21,200.00C
Replacement	MLG Brake Hoses - Replace		Mandatory	5y	13,295.60h/ 13,052.00C/ 07-09-2014	.84year	07-09-2019
Inspection	MLG Insp, LH		Mandatory	8,000.00C 6y	13,145.90h/ 12,839.00C/ 10-22-2012	7,567.00C/ .12year	20,839.00C/ 10-22-2018
Inspection	MLG Insp, RH		Mandatory	8,000.00C 6y	13,145.90h/ 12,839.00C/ 10-22-2012	7,567.00C/ .12year	20,839.00C/ 10-22-2018
Inspection	NLG Insp		Mandatory	8,000.00C 6y	13,145.90h/ 12,839.00C/ 10-22-2012	7,567.00C/ .12year	20,839.00C/ 10-22-2018

Total Air Group

2456 Winchester Rd Hgr 14
 Memphis, Tennessee 38116

September 07, 2018

Telephone: 901-396-9707

Fax: 901-396-9708

Tail Number: N335TA		Manufacturer: Raytheon Aircraft Company		Model: 200		Description: SUPER KINGAIR	
Event	Event Description	ATA	Status	Frequency	Last Compliance	Remaining	Compliance Due
Inspection	Landing Gear, Clevis - Inspection		Mandatory	1,000.00C	13,145.90h/ 12,839.00C/ 10-22-2012	567.00C	13,839.00C
Inspection	Landing Gear, Drag Brace Inspection		Mandatory	8,000.00C 6y	13,145.90h/ 12,839.00C/ 10-22-2012	7,567.00C/ .12year	20,839.00C/ 10-22-2018
Special Checks	Landing Gear, Act Screw Endplay Check		Mandatory	1,000.00C 30m	13,354.50h/ 13,130.00C/ 08-05-2016	858.00C/ 4.94month	14,130.00C/ 02-05-2019
Inspection	Landing Gear, Actuator Mechanical 30mo		Mandatory	1,000.00C 30m	13,354.50h/ 13,130.00C/ 08-05-2016	858.00C/ 4.94month	14,130.00C/ 02-05-2019
Overhaul	Landing Gear, Actuator Mechanical 6yr - Overhaul or Replace		Mandatory	8,000.00C 6y	13,145.90h/ 12,839.00C/ 10-22-2012	7,567.00C/ .12year	20,839.00C/ 10-22-2018
Inspection	Landing Gearbox & Clutch Inspection		Mandatory	8,000.00C 6y	13,145.90h/ 12,839.00C/ 10-22-2012	7,567.00C/ .12year	20,839.00C/ 10-22-2018
Special Checks	O2 cyl Hydro 3HT Steel		Mandatory		13,613.30h/ 13,272.00C/ 08-29-2018		
Replacement	O2 cyl Replace 3HT Steel		Mandatory	24y			
Overhaul	O2 Regulator OH		Mandatory	60m	13,477.30h/ 09-06-2017	47.97month	09-06-2022
Overhaul	O2 Pax Shutoff Valve OH		Mandatory	48m	13,145.90h/ 12,839.00C/ 10-22-2012	22.52monthOVD	10-22-2016
Inspection	Panels, edge lighted (Cockpit) Inspection		Mandatory	2,000.00H 48m	13,354.50h/ 13,130.00C/ 08-05-2016	1,741.20h/ 22.94month	15,354.50h/ 08-05-2020
Inspection	Panels, edge lighted CB Inspection		Mandatory	12m	13,477.30h/ 09-06-2017	.03monthOVD	09-06-2018
Inspection	Panels, edge lighted Fuel Control Lower Inspection		Mandatory	12m	13,477.30h/ 09-06-2017	.03monthOVD	09-06-2018
Special Checks	Ram Air Recovery Insp/Lube		Mandatory	200.00H	13,332.60h/ 13,086.00C/ 12-30-2014	80.70h/ OVD	13,532.60h
Inspection	Aft Press Bulkhead Fuselage Inspection, Special Inspection 51		Mandatory	500.00C	13,295.60h/ 13,052.00C/ 07-09-2014	280.00C	13,552.00C
Replacement	Rudder Boost Filter Replacement		Mandatory	200.00H	13,477.30h/ 09-06-2017	64.00h	13,677.30h

Total Air Group

2456 Winchester Rd Hgr 14
 Memphis, Tennessee 38116

September 07, 2018

Telephone: 901-396-9707

Fax: 901-396-9708

Tail Number: N335TA		Manufacturer: Raytheon Aircraft Company		Model: 200		Description: SUPER KINGAIR	
Event	Event Description	ATA	Status	Frequency	Last Compliance	Remaining	Compliance Due
Inspection	Skins, Exterior Airframe Inspection		Mandatory	1,000.00C	13,295.60h/ 13,052.00C/ 07-09-2014	780.00C	14,052.00C
Inspection	Spar Cap Inspection		Mandatory	12m	13,477.30h/ 09-06-2017	.03monthOVD	09-06-2018
Inspection	Throttle Lever Stop Pin Insp		Mandatory	1,200.00H	13,613.30h/ 13,272.00C/ 08-29-2018	1,200.00h	14,813.30h
Replacement	Windshield Screws Replace		Mandatory	10,000.00C	11,215.30h/ 11,200.00C/ 11-16-2002	7,928.00C	21,200.00C
Inspection	Wing Bolt, Insp		Mandatory	60m	13,295.60h/ 13,052.00C/ 07-09-2014	10.06month	07-09-2019
Replacement	Wing Bolt, Replace		Mandatory	180m	13,295.60h/ 13,052.00C/ 07-09-2014	130.06month	07-09-2029
Special Checks	Wing Bolt, Inconel, Lube		Mandatory	12m	13,354.50h/ 13,130.00C/ 08-05-2016	13.06monthOVD	08-05-2017
Inspection	Frames, Sub-Floor, Insp		Mandatory	1,000.00C	13,613.30h/ 13,272.00C/ 08-29-2018	1,000.00C	14,272.00C
Inspection	Frames, Web Fuselage, Insp		Mandatory	1,000.00C	13,295.60h/ 13,052.00C/ 07-09-2014	780.00C	14,052.00C
Inspection	Windshield, Doublers & Clips Insp		Mandatory	1,000.00C	13,295.60h/ 13,052.00C/ 07-09-2014	780.00C	14,052.00C
Inspection	Emergency Door Hatch Insp		Mandatory	1,000.00C	13,613.30h/ 13,272.00C/ 08-29-2018	1,000.00C	14,272.00C
Inspection	Frames, Fuselage Sta 84 - 374.75 Inspection		Mandatory	1,000.00C	13,295.60h/ 13,052.00C/ 07-09-2014	780.00C	14,052.00C
Inspection	Frames, Fuselage Sta 179 - 271 Inspection		Mandatory	2,500.00C	11,215.30h/ 11,200.00C/ 11-16-2002	428.00C	13,700.00C
Inspection	Door, Cabin Inspection		Mandatory	5,000.00C	13,295.60h/ 13,052.00C/ 07-09-2014	4,780.00C	18,052.00C

Aircraft Status

Total Air Group

2456 Winchester Rd Hgr 14
Memphis, Tennessee 38116

September 07, 2018

Telephone: 901-396-9707

Fax: 901-396-9708

Tail Number: N335TA		Manufacturer: Raytheon Aircraft Company		Model: 200		Description: SUPER KINGAIR	
Event	Event Description	ATA	Status	Frequency	Last Compliance	Remaining	Compliance Due
Special Checks	Lube, 200 hr		Mandatory	200.00H	13,145.90h/ 12,839.00C/ 10-22-2012	267.40h/ OVD	13,345.90h
Special Checks	Lube, 400 hr		Mandatory	400.00H	13,145.90h/ 12,839.00C/ 10-22-2012	67.40h/ OVD	13,545.90h
Special Checks	Lube, 600 hr		Mandatory	600.00H	13,145.90h/ 12,839.00C/ 10-22-2012	132.60h	13,745.90h
Special Checks	Lube, 800 hr		Mandatory	800.00H	13,145.90h/ 12,839.00C/ 10-22-2012	332.60h	13,945.90h
Special Checks	Lube, 1200 hr		Mandatory	1,200.00H	13,145.90h/ 12,839.00C/ 10-22-2012	732.60h	14,345.90h
Overhaul	Overhaul - Landing Gear Motor - to coincide with gearbox inspection		Mandatory	8,000.00C 6y	12,839.30h/ 12,598.00C/ 06-18-2008	7,326.00C/ 4.22yearOVD	20,598.00C/ 06-18-2014
Overhaul	Overhaul - LH Starter-Generator p/n: 23048-016, s/n: 17878		Mandatory	1,000.00H	12,237.40h/ 02-14-2007	9.40h/ OVD	13,237.40h
Replacement	Replacement - LH Impeller		Mandatory	20,000.00C		8,192.00C	20,000.00C
Overhaul	Overhaul - LH Engine		Mandatory	3,000.00H	11,766.70h/ 10,499.00C/ 10-05-2005	1,519.90h	14,766.70h
Replacement	Replacement - LH Oil Filter		Mandatory	1,000.00H	12,744.60h/ 09-01-2010	497.80h	13,744.60h
Replacement	Replacement - LH P3 Filter		Mandatory	1,000.00H	12,744.60h/ 09-01-2010	497.80h	13,744.60h
Replacement	Replacement - LH Flammable Fluid Hoses		Mandatory	5y	12,029.50h/ 05-09-2006	7.33yearOVD	05-09-2011
Replacement	Replacement - LH Engine Mounts		Mandatory	4,000.00H	12,966.90h/ 12-30-2014	3,720.10h	16,966.90h
Replacement	Replacement - LH 2nd Stage PT Disc		Mandatory	8,000.00C	11,766.70h/ 10,499.00C/ 10-05-2005	6,691.00C	18,499.00C
Overhaul	Overhaul - LH Overspeed Gov		Mandatory	6,500.00H	11,766.70h/ 10,499.00C/ 10-05-2005	5,019.90h	18,266.70h
Overhaul	Overhaul - LH Propeller Gov		Mandatory	4,500.00H	11,766.70h/ 10,499.00C/ 10-05-2005	3,019.90h	16,266.70h

Total Air Group

2456 Winchester Rd Hgr 14
 Memphis, Tennessee 38116

September 07, 2018

Telephone: 901-396-9707

Fax: 901-396-9708

Tail Number: N335TA		Manufacturer: Raytheon Aircraft Company		Model: 200		Description: SUPER KINGAIR	
Event	Event Description	ATA	Status	Frequency	Last Compliance	Remaining	Compliance Due
Overhaul	Overhaul - LH Fuel Nozzles		Mandatory	400.00H	13,246.80h/ 11,808.00C/ 08-29-2018	400.00h	13,646.80h
Special Checks	Hydro - LH Eng Fire Bottle		Mandatory	5y	13,111.50h/ 09-06-2017	4year	09-06-2022
Replacement	Replacement - LH Eng Fire Bottle Squib		Mandatory	10y	03-01-2012	3.48year	03-01-2022
Replacement	Replacement - LH 1st Stage PT Disc		Mandatory	8,000.00C	10,499.00C/ 09-27-2005	6,691.00C	18,499.00C
Replacement	Replacement - CT Disc		Mandatory	20,000.00C		8,192.00C	20,000.00C
Replacement	Replacement - LH 1st Stage Compressor Disc		Mandatory	20,000.00C	796.00C/ 09-27-2005	8,988.00C	20,796.00C
Replacement	Replacement - LH 2nd Stage Compressor Disc		Mandatory	20,000.00C	10,499.00C/ 09-27-2005	18,691.00C	30,499.00C
Replacement	Replacement - LH 3rd Stage Compressor Disc		Mandatory	20,000.00C	10,499.00C/ 09-27-2005	18,691.00C	30,499.00C
Inspection	Inspection - LH Engine HSI		Mandatory	1,500.00H	11,766.70h/ 10,499.00C/ 10-05-2005	19.90h	13,266.70h
Overhaul	Overhaul - RH Starter-Generator		Mandatory	1,000.00H	12,279.90h/ 02-14-2007	9.40h/ OVD	13,279.90h
Inspection	Inspection - RH Engine HSI		Mandatory	1,500.00H	12,021.00h/ 11,338.00C/ 03-14-2006	231.70h	13,521.00h
Overhaul	Overhaul - RH Engine		Mandatory	3,000.00H	11,766.70h/ 10,499.00C/ 04-06-2005	1,477.40h	14,766.70h
Replacement	Replacement - RH Oil Filter		Mandatory	1,000.00H	12,665.80h/ 11-11-2009	376.50h	13,665.80h
Replacement	Replacement - RH Impeller		Mandatory	20,000.00C	11,100.00C/ 03-29-2005	18,662.00C	31,100.00C
Replacement	Replacement - RH 3rd Stage Compressor Disc		Mandatory	20,000.00C	11,100.00C/ 03-29-2005	18,662.00C	31,100.00C
Replacement	Replacement - RH 2nd Stage Compressor Disc		Mandatory	20,000.00C	11,100.00C/ 03-29-2005	18,662.00C	31,100.00C
Replacement	Replacement - RH 1st Stage Compressor Disc		Mandatory	20,000.00C	-5,629.00C/ 03-29-2005	1,933.00C	14,371.00C
Replacement	Replacement - RH CT Disc		Mandatory	20,000.00C	685.00C/ 03-29-2005	8,247.00C	20,685.00C
Replacement	Replacement - RH 1st Stage PT Disc (P/N: 3029312)		Mandatory	30,000.00C	-16,602.00C/ 03-29-2005	960.00C	13,398.00C
Replacement	Replacement - RH Eng Fire Bottle Squib		Mandatory	10y	05-01-2012	3.65year	05-01-2022

Total Air Group

2456 Winchester Rd Hgr 14
 Memphis, Tennessee 38116

September 07, 2018

Telephone: 901-396-9707

Fax: 901-396-9708

Tail Number: N335TA		Manufacturer: Raytheon Aircraft Company		Model: 200		Description: SUPER KINGAIR	
Event	Event Description	ATA	Status	Frequency	Last Compliance	Remaining	Compliance Due
Replacement	Replacement - RH P3 Filter		Mandatory	1,000.00H	13,289.30h/ 12,438.00C/ 08-29-2018	1,000.00h	14,289.30h
Replacement	Replacement - RH Flammable Fluid Hoses		Mandatory	5y	12,072.00h/ 05-09-2006	7.33yearOVD	05-09-2011
Replacement	Replacement - RH Engine Mounts		Mandatory	4,000.00H	13,009.40h/ 12-30-2014	3,720.10h	17,009.40h
Replacement	Replacement - RH 2nd Stage PT Disc		Mandatory	8,000.00C	5,242.00C/ 03-29-2005	804.00C	13,242.00C
Overhaul	Overhaul - RH Overspeed Gov		Mandatory	6,500.00H	11,673.40h/ 11,100.00C/ 04-06-2005	4,884.10h	18,173.40h
Overhaul	Overhaul - RH Propeller Gov		Mandatory	4,500.00H	11,673.40h/ 11,100.00C/ 04-06-2005	2,884.10h	16,173.40h
Overhaul	Overhaul - RH Fuel Nozzles		Mandatory	400.00H	13,289.30h/ 12,438.00C/ 08-29-2018	400.00h	13,689.30h
Special Checks	Hydro - RH Eng Fire Bottle		Mandatory	5y	13,154.10h/ 09-06-2017	4year	09-06-2022
Special Checks	LH Propeller Dress & Paint		Mandatory	200.00H	12,173.30h/ 12-30-2014	1,240.00h/ OVD	12,373.30h
Special Checks	Lube - LH Prop		Mandatory	12m	13,613.30h/ 08-29-2018	11.71month	08-29-2019
Inspection	Inspection - LH Raisbeck Prop Inspection		Mandatory	200.00H	13,613.30h/ 08-29-2018	200.00h	13,813.30h
Overhaul	Overhaul - LH Prop		Mandatory	3,000.00H/72 m		385.50h/ 152.19monthOVD	13,998.80h/ 01-01-2006
Inspection	Inspection - RH Raisbeck Prop Inspection		Mandatory	200.00H	9,427.60h/ 08-29-2018	200.00h	9,627.60h
Overhaul	Overhaul - RH Prop		Mandatory	3,000.00H/72 m	8,820.40h/ 08-31-2010	2,392.80h/ 24.23monthOVD	11,820.40h/ 08-31-2016
Special Checks	Lube - RH Prop		Mandatory	12m	9,427.60h/ 08-29-2018	11.71month	08-29-2019
Special Checks	RH Prop Dress & Paint		Mandatory	200.00H	1,174.50h/ 09-06-2017	8,053.10h/ OVD	1,374.50h

*** End of Document ***