

N3622A  
Hobbs: 3624.7  
T.T. : 9317.9  
03/18/19

Performed Annual inspection. Cleaned & lubed aircraft.  
Replaced ELT batteries next due 03-2021. Checked ELT IAW 91.2074 (d).  
Performed gear retract test Emergency & normal. Operation normal.  
Removed & reinstalled left Aux fuel cell after repair by Floats & Fuel Cells Inc.  
Replaced fear up light assy MS25041-2. C/W AD 2007-08-08 inspection of Uplock rollers.  
C/W AD 2004-25-16R1 inspection of heater fuel regulator.  
All Ad's checked.

I certify that this aircraft N3622A has been inspected in accordance with  
An Annual Inspection and was determined to be in an airworthy condition.

Rushing Aviation	Kevin Rushing
703 Airport Rd.	
Marks, MS 38646	IA3412822

N3622A  
Left Engine  
Hobbs: 3624.7  
TSMOH: 672.6  
03/18/19

Performed Annual inspection. Comp 80/ 1/78 2/74 3/77 4/78 5/78 6/61  
Changed oil & filter Aeroshell W100Plus & CH 48108-1. Cut open filter no discrepancies found.  
Checked timing, Cleaned fuel injectors. Cleaned & gapped spark plugs. Replaced Intake air filter BA6205.  
Replaced left CHT Probe 102-0007. Replaced EGT probe 86245. up no leaks noted. All Ad's C/W.

I certify that this Engine has been inspected in accordance with  
An Annual Inspection and was determined to be in an airworthy condition.

Rushing Aviation	Kevin Rushing
703 Airport Rd.	
Marks, MS 38646	IA3412822

N3622A  
Left Propeller  
Hobbs: 3624.7  
TSMOH: 672.7  
03/18/19

Lubed & dressed blades

I certify that this Propeller has been inspected in accordance with  
An Annual Inspection and was determined to be in an airworthy condition.

Rushing Aviation	Kevin Rushing
703 Airport Rd.	
Marks, MS 38646	IA3412822

N3622A  
Right Engine  
Hobbs: 3624.7  
TSMOH: 386.2  
03/18/19

Performed Annual inspection. Comp 80/ 1/69 2/74 3/79 4/78 5/79 6/77  
Changed oil & filter Aeroshell W100Plus & CH48108-1. Cut open filter no discrepancies found.  
Cleaned & gapped spark plugs. Checked timing. Cleaned fuel injectors. Replaced Intake Air filter BA6205.  
Replaced Tach drive seal. Run up no leaks noted. All Ad's C/W.

I certify that this Engine has been inspected in accordance with  
An Annual Inspection and was determined to be in an airworthy condition.

Rushing Aviation  
703 Airport Rd.  
Marks, MS 38646

Kevin Rushing  
  
IA3412822

N3622A  
Right Hobbs: 3624.7  
TSMOH: 386.2  
03/18/19

Lubed & Dressed Blades

I certify that this Propeller has been inspected in accordance with  
An Annual Inspection and was determined to be in an airworthy condition.

Rushing Aviation  
703 Airport Rd.  
Marks, MS 38646

Kevin Rushing  
  
IA3412822